

# SERVICE INFORMATION

# BRAVOR BONAMAT


Page 1 of 1

NO : 5.  
 TITLE : Canister spring  
 MODEL : All FreshMore dispensers  
 DATE : 10-09-2008

## Reason for sending this information

Changes within the Freshbrew-coffee canister and therefor new article number.

The old spring is replace by an other bigger one, which will prevent the tunnel effect of the Freshbrew-coffee better.



## Part Information

This service info will apply to both dispenser and spare parts:

- All FreshMore dispensers with production tracking number 20000.909.262 and higher.
- All spare parts 6.000.229.108 (outlet on the left-hand side) and 6.000.229.123 (outlet on the right-hand side), that will be produced starting week 36 (September 01 2008).

## New Spare Part

- 6.000.229.123 will replace 6.000.229.110 and 6.000.229.108 as Freshbrew-coffee canister

**NOTE:** For the replacement of the 6.000.229.108 dismount A and B and swap these parts then assemble again.

- 6.000.229.132 Drive shaft assy

## Deleted Spare Part

- None